

Inspection Photos

Loc#335344

Operator: Caerus

Insp#:692403350

Insp Date: 4/29/21



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from entry.

April 29, 2021



Photo#2:
Interim area.



Photo#3:
Interim area.

April 29, 2021