

Inspection Photos

Loc#335312

Operator: Caerus

Insp#:692403351

Insp Date: 4/29/21



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location .

April 29, 2021



Photo#2:
Tank Containment area.



Photo#3:
Tank Containment area.

April 29, 2021



Photo#4:
Interim area.

April 29, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Lazier Loc#335312