

Inspection Photos
Location Name: Anne State #6
Location ID: 326750



Colorado Oil and Gas Conservation Commission
40.23778, -104.25146, 4567.2ft, 250°
04/29/2021 11:45:27



Colorado Oil and Gas Conservation Commission
40.23787, -104.25154, 4560.5ft, 209°
04/29/2021 11:45:40

Photo 1 – Tank Battery

Photo 2 – Tank Battery Signs

Inspection Photos
Location Name: Anne State #6
Location ID: 326750



Photo 3 – Gas Meter

Photo 4 – Gas Meter Calibration Card NOT Present

Inspection Photos
Location Name: Anne State #6
Location ID: 326750



Photo 5 – Separator and ECD

Photo 6 – Riser NOT Marked

Inspection Photos
Location Name: Anne State #6
Location ID: 326750



Photo 7 – Stained Soil at Separator

Photo 8 – Unused Engine Parts

Inspection Photos
Location Name: Anne State #6
Location ID: 326750



Photo 9 – Stained Soil at Gas Engine Exhaust

Photo 10 – Stained Soil at Gas Engine and Wildlife Netting missing

Inspection Photos
Location Name: Anne State #6
Location ID: 326750




Photo 11 – Wellhead Stained Soil