

Inspection Photos
Location Name: Vera 1
Location ID: 318556



Photo 1 – Wellhead



Photo 2 – Tank Battery Signs



Inspection Photos
Location Name: Vera 1
Location ID: 318556



Photo 3 – Pumping Unit



Photo 4 – Tank Battery - Weeds



Inspection Photos
Location Name: Vera 1
Location ID: 318556



Photo 5 – Wood Debris/Trash. Tank Labels Fading



Photo 6 – Tank Labels are Fading

Inspection Photos
Location Name: Vera 1
Location ID: 318556




Photo 7 – Unmarked Risers at Separator




Photo 8 – Unmarked Risers at Separator

