

**Inspection Photos**  
**Location Name: Seyfried #2 Tank Battery**  
**Location ID: 470277**



**Photo 1 – Tank Battery – H2O Tank missing Content and Capacity**

**Photo 2 – Tank Battery Signs**



**Inspection Photos**  
**Location Name: Seyfried #2 Tank Battery**  
**Location ID: 470277**




**Photo 3 – Tank Battery – Unused Heater**


**Photo 4 – Separator**



**Inspection Photos**  
**Location Name: Gordon 1**  
**Location ID: 326779**



**Photo 5 – Unmarked Risers at Separator**



**Photo 6 – Gas Meter Calibration Card missing**

