

Inspection Photos
Location Name: 1-4N-64W NESW Amigo Farms TB
Facility ID: 479883



Photo #1 Production Equipment



Photo #2 Tank Battery



Inspection Photos
Location Name: 1-4N-64W NESW Amigo Farms TB
Facility ID: 479883



Photo #3 Meter not calibrated annually



Photo #4 Weathered Berm

Inspection Photos
Location Name: 1-4N-64W NESW Amigo Farms TB
Facility ID: 479883



Photo #5 Weathered Berm

