

Inspection Photos
Location Name: Oxnard East 3130-12CH
Location ID: 425516



Photo 1: Location Sign



Photo 2: Pumpjack

Inspection Photos
Location Name: Oxnard East 3130-12CH
Location ID: 425516



Photo 3: Tank Battery



Photo 4: Storage of equipment

Inspection Photos
Location Name: Oxnard East 3130-12CH
Location ID: 425516



Photo 5: Storage of equipment



Photo 6: No bird protector