

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/04/2021

Submitted Date:

05/05/2021

Document Number:

691201480

**FIELD INSPECTION FORM**Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
Graber, Candice (Nikki) 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

5 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Knop, Max	303-825-4822	MKnop@kpk.com	
, KPK		cogcc@kpk.com	All Inspections
Canfield, Chris		chris.canfield@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
477024	SPILL OR RELEASE	AC	07/06/2020		-	Lawrence Totems Consolidation Line	EI

**General Comment:**

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. No changes since previous inspections.

Photos attached to document site conditions.

Inspected Facilities									
Facility ID:	477024	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI

--

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: Spill remains open. No evidence of remedial work completed on site.

Corrective Action: Per COA on Form 19 Document # 402436530: The Operator shall submit a Form 19 Supplemental Report that documents the successful Remediation of the release within 45 days of the release date (by August 6, 2020). Supporting documentation shall include confirmation soil samples to document removal of impacts from soil in the release area and a site diagram that illustrates the release extent and location of confirmation soil samples. Confirmation soil samples should be collected and analyzed in accordance with Rule 915. If ground water impacts are discovered, the Operator shall submit a Form 27 Site Investigation and Remediation Workplan for the investigation and remediation of impacts to ground water in accordance with Rule 912. 909.c.

Date: 08/06/2020

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Waste Management:**

Type Management Condition GPS (Lat) (Long)

Oily Soil	Piles	Inadequate		
-----------	-------	------------	--	--

Comment: Approximately 1 cubic yard of impacted soil is stockpiled on location with no BMP's present.

Corrective Action: Manage waste in compliance with Rule 913.b.iv and COGCC Guidance 913.b.(5)B i-v

Date: 05/03/2021**Spill/Remediation:**

Comment: Per Form 27 Document #402649657, no work has been conducted at this location and impacted soils remain in situ. Form 27 also indicates that site investigation and remediation began on 08/11/2020. No field evidence or documentation of remedial efforts is available.

Corrective Action: In accordance with 913.d.(1) Operator will investigate impacts to soil, Groundwater, and surface water as soon as the impacts are discovered (8/11/2020). Operator is required by Rule 901.d.(1) to provide a specific implementation schedule, this was not updated on Form 27 Document #402649657. Operator shall submit the updated schedule by 5/3/2021.

Date: 08/11/2021

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://ogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691201481	Location Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5421379">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5421379</a>