

Inspection Photos  
H. Huett Consolidation Release  
Spill ID 478005 (AC)



Colorado Oil and Gas Conservation Commission  
40.0434, -104.85528, 4889.1ft, 39°  
05/04/2021 10:15:04 AM

**Photo 1 – Spill area. Fencing down around open excavation.**



Colorado Oil and Gas Conservation Commission  
40.04344, -104.8552, 4891.2ft, 33°  
05/04/2021 10:15:15 AM

**Photo 2 – Spill excavation. Impacts appear to remain in situ. Groundwater observed in open excavation.**

Inspection Photos  
H. Huett Consolidation Release  
Spill ID 478005 (AC)



**Photo 3 – Spill excavation. Impacts appear to remain in situ. Groundwater observed in open excavation.**

**Photo 4 – Exposed flowline in open excavation.**

Inspection Photos  
H. Huett Consolidation Release  
Spill ID 478005 (AC)



**Photo 5 – Spill excavation. Impacts appear to remain in situ. Groundwater observed in open excavation.**

**Photo 6 – Trash on location.**