

Inspection Photos

Location Name: Facility 4 West A Consolidation Line

Spill ID: 459299



Photo 1 Approximate reported coordinates of Spill, looking south.



Photo 2 Amoco pipeline marker near reported Spill coordinates.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources