

Final Reclamation Inspection

April 29, 2021

Operator: NOBLE ENERGY INC - #100322

Location ID: 329296

Inspection Document #: 697502828

Weld County, CO

SWSE Section 32 T7N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: OTTOSON #32-15
Location ID: 329296



Photo 1. Photo taken from the well location, facing East. Photo illustrates the well location is not reflective of reference areas- with bare patches and some annual weeds.



Inspection Photos
Location Name: OTTOSON #32-15
Location ID: 329296



Photo 2. Photo taken adjacent from the well location, facing East. Photo illustrates bare patches extending eastwards which appear to be from flowline removal.



Inspection Photos
Location Name: OTTOSON #32-15
Location ID: 329296



Photo 3. Reference photo taken south of the well location, facing South. See comments under Photo 1.



Inspection Photos
Location Name: OTTOSON #32-15
Location ID: 329296



Photo 4. Photo taken from the associated offsite tank battery location, facing West. Photo illustrates the tank battery location is still in use for other nearby wells.

