

Inspection Photos
Location Name: State 2-12
Location ID: 328919



Photo 1 – Wellhead Sign

Photo 2 – Wildlife Netting missing

Inspection Photos
Location Name: State 2-12
Location ID: 328919



Photo 3 – Wellhead



Photo 4 – Pumping Unit