

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/06/2021

Submitted Date:

05/06/2021

Document Number:

699103570

**FIELD INSPECTION FORM**Loc ID 330198 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

11 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
250804	WELL	TA	09/21/2016	OW	123-18607	MONFORT BB #30-12	TA

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	Wire		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Wire		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		

Comment:		
Corrective Action:		Date:
Type: Emission Control Device	# 2	
Comment:		
Corrective Action:		Date:
Type: Pig Station	# 1	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment:	Appears to be plumbed to surface.	
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.368300,-104.488100
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	OTHER	STEEL AST		,
Comment:	Shares containment with other crude oil tank.				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	210 BBL
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Comment:							
Corrective Action:							Date:
Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	1	OTHER	PBV CONCRETE		,		
Comment:		Shares containment with crude oil tanks.					
Corrective Action:							Date:

**Paint**

Condition							
Other (Content)							
Other (Capacity)	48 BBL						
Other (Type)							

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Comment:							
Corrective Action:							
		Date:					

**Venting:**

Yes/No	NO						
Comment:							
Corrective Action:						Date:	

**Flaring:**

Type						
Comment:						
Corrective Action:						Date:

**Inspected Facilities**Facility ID: 250804 Type: WELL API Number: 123-18607 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: T/A

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**Date of Last Brhd Test: 02/21/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday 5/6/21 at approximately 0750hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Monfort BB 30-12 of Noble Energy Location ID: 330198 in Weld County, Colorado.</p> <p>While there, I observed a well that is T/A</p> <p>No violation of the COGCC rules were observed at the time of inspection.</p> <p>This is a summary of inspection report.</p>	burnsa	05/06/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699103571	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5422643">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5422643</a>