

Inspection Photos
Location Name: Zimmerman/Chamberlin 1
Location ID: 313011



Photo 1. Overview of location taken facing west.



Photo 2. No bradenhead access apparent. Stained soil at wellhead. Tubing stored at wellhead.

