

Inspection Photos
Location Name: Neff 1
Location ID: 336842



Photo 1 WH sign

Photo 2 WH

Inspection Photos
Location Name: Neff 1
Location ID: 336842




Photo 3 Stained soil around WH

Photo 2 Stained soil by WH

Inspection Photos
Location Name: Neff 1
Location ID: 336842



Photo 5 dead weeds in front WH

Photo 6 No containment under drum in case of leak

Inspection Photos
Location Name: Neff 1
Location ID: 336842



Photo 7 Electric panel, meter box and transformer

Photo 8 Pump jack