

Inspection Photos
Location Name: Duncan Unit 1-4
Location ID: 313121



Photo 1. Overview of location taken facing south.



Photo 2. No bradenhead access apparent.

