


**Inspection Photos**  
**Location Name: Duncan Unit 2 1**  
**Location ID: 312827**



**Photo 1. Overview of location taken facing south.**



**Photo 2. No bradenhead access apparent.**

