

TEP
Broome 1
Location # 335227



location



location



TEP
Broome 1
Location # 335227



location



Lack of stabilization/compaction



**TEP
Broome 1
Location # 335227**



Cut slope lack of stabilization/erosion photo from previous inspection



Cut slope lack of stabilization/erosion photo from follow up inspection



TEP
Broome 1
Location # 335227



Cut slope lack of stabilization/erosion photo from previous inspection



Cut slope lack of stabilization/erosion photo from follow up inspection



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

TEP
Broome 1
Location # 335227



Cut slope lack of stabilization/erosion

