

# Inspection Photos

5/6/2021

Operator: SG INTERESTS I LTD - 77330

Location ID: 422990

Gunnison County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 422990



**Photo 1:** Photo taken from the Location entrance. Get to Location was open prior to inspector accessing site. Inspector closed gate upon completion of inspection and leaving Location.



Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 422990



**Photo 2:** Photo taken from the cut slopes on the north end of the Location, facing north. Previous inspections documented that control measures to protect/stabilize slopes on the Location were missing or insufficient. Photo shows control measures to protect/stabilize slopes on the Location remain missing or insufficient.





Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 422990



**Photo 3:** Photo taken from the cut slopes on the northeast end of the Location. See comments under photo 1.



Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 422990



**Photo 4:** Photo taken from the cut slopes on the northeast end of the Location. See comments under photo 1.



Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 422990



**Photo 5:** Photo taken from the cut slopes on the northeast end of the Location. See comments under photo 1.



Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 422990



**Photo 6:** Photo taken from the cut slopes on the northeast end of the Location. See comments under photo 1.



Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 422990



**Photo 7:** Photo taken from the cut slopes on the northeast end of the Location. See comments under photo 1.



Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 422990



**Photo 8:** Photo taken from the southeast corner of the Location. Photo shows slope drain. Previous inspections documented that the slope drain was not been constructed with an appropriate outlet per good engineering practices. Photo shows slope drain has not been constructed with an appropriate outlet. Photo also shows slope drain has not been properly secured.





Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 422990



**Photo 9:** Continued from photo 8.



Inspection Photos  
Operator Name: SG INTERESTS I LTD - 77330  
Location ID: 422990



**Photo 10:** Photo taken from the southwest corner of the Location. Photo shows slope drain. Previous inspections documented that the slope drain was not been constructed with an appropriate outlet per good engineering practices. Photo shows slope drain has not been constructed with an appropriate outlet. Photo also shows slope drain has not been properly secured.

