

Inspection Photos

API: 009-06175

Operator: SOVEREIGN OPERATING COMPANY

Inspection Date: 5/5/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06175 | Date: 5/5/2021

Inspection Photos



Photo 1. Facing north along the former access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06175 | Date: 5/5/2021

Inspection Photos



Photo 2. Facing north toward the location. Desirable vegetation cover has not established at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06175 | Date: 5/5/2021

Inspection Photos




Photo 3. Facing east at the location. The dark green vegetation emerging undesirable weeds. (Kochia).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06175 | Date: 5/5/2021

Inspection Photos



Photo 4. View of ground cover shows undesirable weeds establishing (Kochia).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06175 | Date: 5/5/2021

Inspection Photos



Photo 5. Facing toward the surrounding reference area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06175 | Date: 5/5/2021