

Inspection Photos
Location Name: Thornton 44-5
Spill ID: 479926



Photo 1 – Location overview



Photo 2 – Wellhead and spill area

Inspection Photos
Location Name: Thornton 44-5
Spill ID: 479926




Photo 3 – Hydrocarbon fluids mixed with rainfall on location.



Photo 4 – Absorbent booms placed on downhill area of pad.

Inspection Photos
Location Name: Thornton 44-5
Spill ID: 479926



Photo 5 – Stormwater diversions designed to carry rainwater from the wellhead/spill area.



Photo 6 – Outfall of stormwater diversion.