

Final Reclamation Inspection

May 4, 2021

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

API: 123-20364

Inspection Document #: 697502846

Weld County, CO

NENE Section 26 T2N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: (HSR) VINCENT #1-26A
API: 123-20364



Photo 1. Photo taken from the well location, facing West. Photo illustrates all equipment has been removed from the well location.

Note: COGCC staff did not inspect the associated offsite tank battery because of wet soil conditions- see Photo 2.



Inspection Photos
Location Name: (HSR) VINCENT #1-26A
API: 123-20364



Photo 2. Google Earth aerial imagery from 5/31/2018 post plugging operations. Photo illustrates the well location (red) and flowline/associated offsite tank battery location. COGCC staff will perform a future inspection along the flowline/associated offsite tank battery location.

