

Inspection Photos May 6, 2021

Location Name: Cordes #3 Tank Battery – Spill/Release Inspection (Spill Point #479951)

Spill #402679995

NESW Section 7 – Township 1 South - Range 57 West

Adams County



Photo looking due north to treater.



Photo looking north - tank



Inspection Photos May 6, 2021

Location Name: Cordes #3 Tank Battery – Spill/Release Inspection (Spill Point #479951)
NESW Section 7 – Township 1 South - Range 57 West
Adams County



Fluid removal. Photo looking north



Inspection Photos May 6, 2021

Location Name: Cordes #3 Tank Battery – Spill/Release Inspection (Spill Point #479951)
NESW Section 7 – Township 1 South - Range 57 West
Adams County



Tank. Photo looking NNE



Tank. Photo looking east



Inspection Photos May 6, 2021

**Location Name: Cordes #3 Tank Battery – Spill/Release Inspection (Spill Point #479951)
NESW Section 7 – Township 1 South - Range 57 West
Adams County**



Location of berm failure on NE side of containment. Foreground scraped to remove spill material. Photo looking west.



Inspection Photos May 6, 2021

**Location Name: Cordes #3 Tank Battery – Spill/Release Inspection (Spill Point #479951)
NESW Section 7 – Township 1 South - Range 57 West
Adams County**



**Photo looking north along spill path. Foreground scraped to
remove spill material. Pit berm in background**



Inspection Photos May 6, 2021

**Location Name: Cordes #3 Tank Battery – Spill/Release Inspection (Spill Point #479951)
NESW Section 7 – Township 1 South - Range 57 West
Adams County**



Photo looking west along spill path. Bobcat scraping to remove spill material.




Nnorth of Bobcat along spill path. Photo looking SSW. Pit berm on right.



Inspection Photos May 6, 2021

**Location Name: Cordes #3 Tank Battery – Spill/Release Inspection (Spill Point #479951)
NESW Section 7 – Township 1 South - Range 57 West
Adams County**



**Photo looking south along spill path.
Pit berm in background.
Residual material no live fluids**



Inspection Photos May 6, 2021

**Location Name: Cordes #3 Tank Battery – Spill/Release Inspection (Spill Point #479951)
NESW Section 7 – Township 1 South - Range 57 West
Adams County**



**Photo looking NNE along spill path.
Residual material no live fluids
Excavator working on spill clean-up.**



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources