

# Final Reclamation Inspection

May 4, 2021

Operator: CRESTONE PEAK RESOURCES OPERATING LLC - 10633

Location ID: 322560

Inspection Document #: 697502852

Weld County, CO

NWSW Section 19 T2N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation**  
**Commission**

Department of Natural Resources

Inspection Photos  
Location Name: MURATA #4-19 J  
Location ID: 322560



**Photo 1.** Google Earth aerial from 5/31/2018 illustrating active operations.

Inspection Photos  
Location Name: MURATA #4-19 J  
Location ID: 322560



**Photo 2.** Google Earth aerial from 9/29/2020 illustrating conditions after plugging and abandonment. Photo illustrates the Operator has failed to remove all equipment.



Inspection Photos  
Location Name: MURATA #4-19 J  
Location ID: 322560



**Photo 3.** Photo taken from the location, facing North. Photo illustrates all equipment has not been removed.



Inspection Photos  
Location Name: MURATA #4-19 J  
Location ID: 322560



**Photo 4.** Close up photo taken of the equipment.



Inspection Photos  
Location Name: MURATA #4-19 J  
Location ID: 322560



**Photo 5.** Photo taken from the eastern location, facing West. Photo illustrates some establishment of desirable vegetation.



Inspection Photos  
Location Name: MURATA #4-19 J  
Location ID: 322560



**Photo 6.** Reference photo taken west of the location, facing West. Photo illustrates reference areas appear to have been overgrazed and are mostly annual weeds.