

Final Reclamation Inspection

May 4, 2021

Operator: CRESTONE PEAK RESOURCES OPERATING LLC - 10633

Location ID: 336424

Inspection Document #: 697502854

Weld County, CO

NWSW Section 19 T2N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: HEIN W-62N66W 19NWSW
Location ID: 336424



Photo 1. Photo taken from the associated offsite tank battery location, facing Southeast. Photo illustrates all equipment has been removed and little to no establishment of desirable vegetation.

Inspection Photos
Location Name: HEIN W-62N66W 19NWSW
Location ID: 336424



Photo 2. Photo taken from the southern location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: HEIN W-62N66W 19NWSW
Location ID: 336424



Photo 3. Reference photo taken west of the location, facing West. Photo illustrates reference areas appear to have been overgrazed and are mostly annual weeds.