

# Final Reclamation Inspection

May 4, 2021

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

API: 123-16907

Inspection Document #: 697502856

Weld County, CO

NWSW Section 19 T2N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: HEIN W #19-12  
API: 123-16907



**Photo 1.** Photo taken from the southern location, facing North. Photo illustrates all equipment has been removed and little to no establishment of desirable vegetation.



Inspection Photos  
Location Name: HEIN W #19-12  
API: 123-16907



**Photo 2.** Reference photo taken west of the location, facing West. Photo illustrates reference areas appear to have been overgrazed and are mostly annual weeds.