





COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Well.

Continental 3-29

API: 05-103-08215

Inspection: 701500661



39.75303, -108.63527, 7220.9ft, 318°
05/07/2021 02:54:51 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Separator pit, separator, meter building.

Continental 3-29

API: 05-103-08215

Inspection: 701500661




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Well pit.

Continental 3-29

API: 05-103-08215

Inspection: 701500661




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Meter chart #1.

Continental 3-29

API: 05-103-08215

Inspection: 701500661



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 6. Meter chart #2.

Continental 3-29

API: 05-103-08215

Inspection: 701500661