

# Construction and Stormwater Inspection

May 5, 2021

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

Location ID: 479193

Inspection Document #: 697502860

Weld County, CO

SESW Section 16 T8N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Reeman DE Pad  
Location ID: 479193



**Photo 1.** Photo taken from the entrance of location, facing South. Photo illustrates major construction activities have commenced.

Inspection Photos  
Location Name: Reeman DE Pad  
Location ID: 479193



**Photo 2.** Photo taken from the entrance of location, facing East. See comments under Photo 1.