

Final Reclamation Inspection

May 5, 2021

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

Location ID: 317511

Inspection Document #: 697502866

Weld County, CO

SESW Section 27 T8N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: KENNEDY #1
Location ID: 317511



Photo 1. Photo taken from the location, facing South. Photo illustrates Operator performed the corrective action to remove gravel from location. Field is currently fallow; therefore, a future inspection will need to be performed to ensure compliance with Rule 1004 standards.



Inspection Photos
Location Name: KENNEDY #1
Location ID: 317511



Photo 2. Photo taken from the location, facing West. See comments under Photo 1.



Inspection Photos
Location Name: KENNEDY #1
Location ID: 317511



Photo 3. Photo taken from the location, facing North. See comments under Photo 1.

