

# Final Reclamation Inspection

May 5, 2021

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

Location ID: 323392

Inspection Document #: 697502868

Weld County, CO

NESW Section 27 T8N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: PIERCE UNIT-KENNEDY #3  
Location ID: 323392



**Photo 1.** Photo taken from the location. Photo illustrates Operator is in process of plugging operations.

Inspection Photos  
Location Name: PIERCE UNIT-KENNEDY #3  
Location ID: 323392



**Photo 2.** Photo taken from the location, facing Northeast. See comments under Photo 1.

