

Construction and Stormwater Inspection

May 7, 2021

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

Location ID: 479193

Inspection Document #: 697502874

Weld County, CO

SESW Section 16 T8N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources



Photo 1. Drone aerial imagery taken during construction operations. Photo illustrates the topsoil stockpile (orange) and the detention pond (blue).



Photo 2. Drone aerial imagery taken during construction operations. Photo illustrates the access road.



Photo 3. Drone aerial imagery taken during construction operations. Photo illustrates the topsoil stockpile.



Photo 4. Drone aerial imagery taken during construction operations. Photo illustrates the detention pond.

Inspection Photos
Location Name: Reeman DE Pad
Location ID: 479193



Photo 5. Photo taken from the entrance of location, facing East. Photo illustrates construction activities are underway along the access road.

Inspection Photos
Location Name: Reeman DE Pad
Location ID: 479193



Photo 6. Photo taken from the eastern location, facing North. Photo illustrates a ditch BMP which is directed to a detention pond.

Inspection Photos
Location Name: Reeman DE Pad
Location ID: 479193



Photo 7. Photo taken from the western location, facing South. Photo illustrates a ditch BMP which is directed to a detention pond. Photo also illustrates the topsoil stockpile.