

Inspection Photos
Location Name: Bashor PC GQ 17-04
Location ID: 417833



Photo 1 – Pumping Unit



Photo 2 – Wellhead

Inspection Photos
Location Name: Bashor PC GQ 17-04
Location ID: 417833



Photo 3 – Wellhead Sign

Photo 4 – Treater, Gas Meter and ECD

Inspection Photos
Location Name: Bashor PC GQ 17-04
Location ID: 417833



Photo 5 – Battery Sign at Entrance – Noble’s Emergency Number STILL Present

Photo 6 – Tank Battery - H2O Tank missing NFPA Label