

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402683375  
Receive Date:  
05/10/2021

Report taken by:  
BOB CHESSON

Site Investigation and Remediation Workplan (Initial Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27.

This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Refer to Rules 340, 905, 906, 907, 908, 909, and 910

OPERATOR INFORMATION

Name of Operator: NOBLE ENERGY INC	Operator No: 100322	<b>Phone Numbers</b>
Address: 1001 NOBLE ENERGY WAY		Phone: (970) 3045329
City: HOUSTON State: TX Zip: 77070		Mobile: ( )
Contact Person: Jacob Evans	Email: jacob.evans@chevron.com	

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 18024 Initial Form 27 Document #: 402683375

PURPOSE INFORMATION

- 901.e. Sensitive Area Determination
- 909.c.(1), Rule 905: Pit or PW vessel closure
- 909.c.(2), Rule 906: Spill/Release Remediation
- 909.c.(3), Rule 907.e.: Land treatment of oily waste
- 909.c.(4), Rule 908.g.: Centralized E&P Waste Management Facility closure
- 909.c.(5), Rule 910.b.(4): Remediation of impacted ground water
- Rule 909.e.(2)A.: Notice completion of remediation in accordance with Rule 909.b.
- Rule 909.e.(2)B.: Closure of remediation project
- Rule 906.c.: Director request
- Other

SITE INFORMATION

N Multiple Facilities ( in accordance with Rule 909.c. )

Facility Type: LOCATION	Facility ID: 305386	API #:	County Name: WELD
Facility Name: GUTTERSEN STATE CC-64N63W 32SWNW	Latitude: 40.271049	Longitude: -104.468885	
** correct Lat/Long if needed: Latitude: 40.264852		Longitude: -104.466727	
QtrQtr: SWNW	Sec: 32	Twp: 4N	Range: 63W Meridian: 6 Sensitive Area? Yes

SITE CONDITIONS

General soil type - USCS Classifications SW Most Sensitive Adjacent Land Use Rangeland

Is domestic water well within 1/4 mile? No Is surface water within 1/4 mile? No

Is groundwater less than 20 feet below ground surface? No

Other Potential Receptors within 1/4 mile

# SITE INVESTIGATION PLAN

## TYPE OF WASTE:

- |  |  |  |
|--|--|--|
| <input checked="" type="checkbox"/> E&P Waste      | <input type="checkbox"/> Other E&P Waste             | <input type="checkbox"/> Non-E&P Waste |
| <input checked="" type="checkbox"/> Produced Water | <input type="checkbox"/> Workover Fluids             | _____                                  |
| <input type="checkbox"/> Oil                       | <input type="checkbox"/> Tank Bottoms                |  |
| <input type="checkbox"/> Condensate                | <input type="checkbox"/> Pigging Waste               |  |
| <input type="checkbox"/> Drilling Fluids           | <input type="checkbox"/> Rig Wash                    |  |
| <input type="checkbox"/> Drill Cuttings            | <input type="checkbox"/> Spent Filters               |  |
|  | <input type="checkbox"/> Pit Bottoms                 |  |
|  | <input type="checkbox"/> Other (as described by EPA) | _____                                  |

## DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
Yes	SOILS	10' X 12' X 5' TD	Laboratory Analytical

## INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

Noble discovered an unintentional release at the Guttarsen State CC 32-5 tank battery due to a small fracture in the produced water vault. The water vault was removed. An unknown amount of produced water was released, and 31 cubic yards of impacted soil was excavated and transported to a certified landfill for disposal.

## PROPOSED SAMPLING PLAN

### Proposed Soil Sampling

Will soil samples be collected as part of this investigation? ( Number, type (grab/composite), analyses, and locations of samples ):

Grab soil samples will be collected for analysis of Table 915-1 TPH C6-36, metals, organics, and inorganic parameters.

### Proposed Groundwater Sampling

Will groundwater samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

### Proposed Surface Water Sampling

Will surface water samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

## Additional Investigative Actions

Additional alternative investigative actions described in attached Site Investigation Plan ( summary ):

# SITE INVESTIGATION REPORT

## SAMPLE SUMMARY

### Soil

Number of soil samples collected 0  
Number of soil samples exceeding 910-1 \_\_\_\_\_  
Was the areal and vertical extent of soil contamination delineated? \_\_\_\_\_  
Approximate areal extent (square feet) \_\_\_\_\_

### NA / ND

\_\_\_\_\_ Highest concentration of TPH (mg/kg) \_\_\_\_\_  
\_\_\_\_\_ Highest concentration of SAR \_\_\_\_\_  
\_\_\_\_\_ BTEX > 910-1 \_\_\_\_\_  
\_\_\_\_\_ Vertical Extent > 910-1 (in feet) \_\_\_\_\_

### Groundwater

Number of groundwater samples collected 0  
Was extent of groundwater contaminated delineated? No  
Depth to groundwater (below ground surface, in feet) \_\_\_\_\_  
Number of groundwater monitoring wells installed \_\_\_\_\_  
Number of groundwater samples exceeding 910-1 \_\_\_\_\_

\_\_\_\_\_ Highest concentration of Benzene (µg/l) \_\_\_\_\_  
\_\_\_\_\_ Highest concentration of Toluene (µg/l) \_\_\_\_\_  
\_\_\_\_\_ Highest concentration of Ethylbenzene (µg/l) \_\_\_\_\_  
\_\_\_\_\_ Highest concentration of Xylene (µg/l) \_\_\_\_\_  
\_\_\_\_\_ Highest concentration of Methane (mg/l) \_\_\_\_\_

### Surface Water

0 Number of surface water samples collected  
\_\_\_\_\_ Number of surface water samples exceeding 910-1  
If surface water is impacted, other agency notification may be required.

## OTHER INVESTIGATION INFORMATION

Were impacts to adjacent property or offsite impacts identified?

Were background samples collected as part of this site investigation?

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) \_\_\_\_\_ Volume of liquid waste (barrels) \_\_\_\_\_

Is further site investigation required?

# REMEDIAL ACTION PLAN

## SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

The source was removed through excavation of impacted soil. Additional source excavation will be scheduled.

## REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

NA

## Soil Remediation Summary

In Situ

Ex Situ

\_\_\_\_\_ Bioremediation ( or enhanced bioremediation )

Yes \_\_\_\_\_ Excavate and offsite disposal

\_\_\_\_\_ Chemical oxidation

\_\_\_\_\_ If Yes: Estimated Volume (Cubic Yards) \_\_\_\_\_ 100

\_\_\_\_\_ Air sparge / Soil vapor extraction

\_\_\_\_\_ Name of Licensed Disposal Facility or COGCC Facility ID # \_\_\_\_\_

\_\_\_\_\_ Natural Attenuation

\_\_\_\_\_ Excavate and onsite remediation

\_\_\_\_\_ Other \_\_\_\_\_

\_\_\_\_\_ Land Treatment

\_\_\_\_\_ Bioremediation (or enhanced bioremediation)

\_\_\_\_\_ Chemical oxidation

\_\_\_\_\_ Other \_\_\_\_\_

## Groundwater Remediation Summary

\_\_\_\_\_ Bioremediation ( or enhanced bioremediation )

\_\_\_\_\_ Chemical oxidation

\_\_\_\_\_ Air sparge / Soil vapor extraction

\_\_\_\_\_ Natural Attenuation

\_\_\_\_\_ Other \_\_\_\_\_

## GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

\_\_\_\_\_

# REMEDIATION PROGRESS UPDATE

## PERIODIC REPORTING

Frequency:  Quarterly  Semi-Annually  Annually  Other \_\_\_\_\_

Report Type:  Groundwater Monitoring  Land Treatment Progress Report  O&M Report

Other Site Figure \_\_\_\_\_

## WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? Yes

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

NA

Volume of E&P Waste (solid) in cubic yards \_\_\_\_\_ 31

E&P waste (solid) description E&P solid waste derived from excavation activities

COGCC Disposal Facility ID #, if applicable: \_\_\_\_\_

Non-COGCC Disposal Facility: Waste Management

Volume of E&P Waste (liquid) in barrels \_\_\_\_\_ 0

E&P waste (liquid) description \_\_\_\_\_

COGCC Disposal Facility ID #, if applicable: \_\_\_\_\_

Non-COGCC Disposal Facility: \_\_\_\_\_

## RECLAMATION PLAN

### RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Reclamation will be in accordance with the 1000 series rules.

Is the described reclamation complete? No

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim?

Final?

Did the Surface Owner approve the seed mix? \_\_\_\_\_

If NO, does the seed mix comply with local soil conservation district recommendations? \_\_\_\_\_

# IMPLEMENTATION SCHEDULE

## **PRIOR DATES**

Date of Surface Owner notification/consultation, if required. 05/07/2021

Actual Spill or Release date, if known. \_\_\_\_\_

## **SITE INVESTIGATION DATES**

Date of Initial Actions described in Site Investigation Plan (start date). 05/07/2021

Date of commencement of Site Investigation. \_\_\_\_\_

Date of completion of Site Investigation. \_\_\_\_\_

## **REMEDIAL ACTION DATES**

Date of commencement of Remediation. \_\_\_\_\_

Date of completion of Remediation. \_\_\_\_\_

## **SITE RECLAMATION DATES**

Date of commencement of Reclamation. \_\_\_\_\_

Date of completion of Reclamation. \_\_\_\_\_

**OPERATOR COMMENT**

--

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: ` Jacob Evans \_\_\_\_\_

Title: Environmental Specialist \_\_\_\_\_

Submit Date: ` 05/10/2021 \_\_\_\_\_

Email: jacob.evans@chevron.com \_\_\_\_\_

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: BOB CHESSON \_\_\_\_\_

Date: 05/12/2021 \_\_\_\_\_

Remediation Project Number: 18024 \_\_\_\_\_

**Condition of Approval****COA Type****Description**

0 COA	

**Attachment Check List**

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

**Att Doc Num****Name**

402683375	FORM 27-INITIAL-SUBMITTED
402683398	MAP

Total Attach: 2 Files

**General Comments****User Group****Comment****Comment Date**

Environmental	Per Rule 913.d.(2) Operator shall submit a Supplemental Form 27 with an updated Implementation Schedule at least 14 days in advance of any schedule changes.  Operator will submit a specific implementation schedule in accordance with Rule 913.d.	05/12/2021
Environmental	A supplemental Form 27 must be submitted within 90 days of the completion of this environmental investigation.	05/12/2021

Total: 2 comment(s)