

**Inspection Photos**  
**Location Name: Martin T. Hart B Unit 1**  
**Location ID: 317839**



**Photo 1 WH sign**

**Photo 2 WH**

**Inspection Photos**  
**Location Name: Martin T. Hart B Unit 1**  
**Location ID: 317839**



**Photo 3 Pump Jack**

**Photo 4 Ancillary equipment**

**Inspection Photos**  
**Location Name: Martin T. Hart B Unit 1**  
**Location ID: 317839**



**Photo 5 TB sign**

**Photo 6 TB placards faded and peeling**

**Inspection Photos**  
**Location Name: Martin T. Hart B Unit 1**  
**Location ID: 317839**



**Photo 7 Gas Meter Run No indication of calibration.**

**Photo 8 Flow line Manifold**

**Inspection Photos**  
**Location Name: Martin T. Hart B Unit 1**  
**Location ID: 317839**



**Photo 9 Horizontal Heated Separator**