

Inspection Photos
Location Name: Longmont Farms Unit 5
Spill ID: 479267



Photo 1 Well Sign



Photo 2 Excavation at flowline spill looking north



Inspection Photos
Location Name: Longmont Farms Unit 5
Spill ID: 479267



Photo 3 Temporary stockpiled material



Photo 4 Excavation looking east



Inspection Photos
Location Name: Longmont Farms Unit 5
Spill ID: 479267



Photo 5 Excavation looking south