

Inspection Photos
Location Name: Jillson A1
Spill ID: 478617



Photo 1 Well Sign



Photo 2 Leak from open top tank valve



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Jillson A1
Spill ID: 478617



Photo 3 Well with workover platform



Photo 4 Produced water vessel

