

Inspection Photos
Operator: Catamount
API: 067-07909
Date: 5/10/2021



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the northern project area from the northwestern corner facing eastward. Revegetation is progressing with grasses such as western wheatgrass, crested wheatgrass, and sand dropseed.



Photo 3. View of the southern project area from the southwestern corner facing eastward.



Photo 4. View of the reference area comprised of pinyon and juniper woodland with understory of black sagebrush, squirreltail, western wheatgrass, and forbs such as penstemon, and phlox.