

# Inspection Photos

API: 061-06797

Operator: BERRY ENERGY INC

Inspection Date: 5/12/2021



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06797 | Date: 5/12/2021

## Inspection Photos



**Photo 1.** Drone aerial photo facing southwest toward the location. It appears location and surrounding field has been put into crop production. There is no sign of crop establishment at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06797 | Date: 5/12/2021

## Inspection Photos



**Photo 2.** Drone aerial photo facing northeast toward the location. It appears location and surrounding field has been put into crop production. There is no sign of crop establishment at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06797 | Date: 5/12/2021