

Inspection Photos
Location Name: HSR- Strear 2-22
Location ID: 311443



Photo 1 WH sign

Photo 2 WH

Inspection Photos
Location Name: HSR- Strear 2-22
Location ID: 311443



Photo 3 TB sign

Photo 4 TB

Inspection Photos
Location Name: HSR- Strear 2-22
Location ID: 311443



Photo 5 tumble weeds piled up around ECD

Photo 6 tumble weeds piled up around ECD

Inspection Photos
Location Name: HSR- Strear 2-22
Location ID: 311443



Photo 7 Horizontal Heated Separator

Photo 8 Gas Meter Run

