

Inspection Photos

API: 061-06353

Operator: STRACHAN EXPLORATION

Inspection Date: 5/12/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06353 | Date: 5/12/2021

Inspection Photos



Photo 1. Drone aerial photo facing north toward the location (circled).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06353 | Date: 5/12/2021

Inspection Photos



Photo 2. Facing southwest at the location. The location remains mostly devoid of vegetation growth. There is no indication that reclamation was performed. Tanks remain in upper left photo (red arrow).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06353 | Date: 5/12/2021

Inspection Photos



Photo 3. Facing southwest at the location. The location remains mostly devoid of vegetation growth. There is no indication that reclamation was performed. Tanks remain in upper photo (red arrow).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06353 | Date: 5/12/2021

Inspection Photos



Photo 4. Facing north toward the surrounding undisturbed pasture.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06353 | Date: 5/12/2021