

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FRAC TECH-67S96W /27SWNE

Location ID: 334715



Photo #3805 from entrance to location.



Photo #3806 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FRAC TECH-67S96W /27SWNE

Location ID: 334715



Photo #3807 Location lacks stabilization.



Photo #3808 No form of tracking BMP at entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FRAC TECH-67S96W /27SWNE

Location ID: 334715



No battery sign located at the tank battery.