

Inspection Photos
Long Ridge
J15 Spill/Release ID: 474500 Remediation: #15535
Inspection Date: May 6, 2021



Overview of the two structures and steel AST.



Overview of the two structures and steel AST. Note the 2-inch steel pipeline that is attached to both of the structures on location.

Inspection Photos
Long Ridge
J15 Spill/Release ID: 474500 Remediation: #15535
Inspection Date: May 6, 2021



2-inch steel pipeline that is attached to the western structure via processing pipe.



Steel AST inside a lined, earthen containment structure. Note the missing labels. Note the solar panels located next to multiple monitoring wells on location.

