

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/07/2021

Submitted Date:

05/10/2021

Document Number:

691201495

FIELD INSPECTION FORM

Loc ID: 305505 Inspector Name: Graber, Candice (Nikki) On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Greg Hamilton		Gregory_Hamilton@oxy.com	

General Comment:

This is an environmental inspection in response to spill Document #402679111 reported by Operator on 5/3/2021.

Any corrective actions from previous inspections that have not been addressed are still applicable.

There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: Impacted material remains in situ (Photo 2), hydrocarbon mixed rainwater was visible on the ground surface (Photo 3) during inspection. Absorbent booms had been placed on the downhill area of the pad (Photo 4). Stormwater controls (Photos 5 and 6) exist adjacent to the spill area which divert rainwater from the wellhead (spill area); no booms or other controls were placed in the diversion area or downstream to protect runoff.

Corrective Action: Operator shall install controls to protect stormwater runoff as soon as practicable. Prior to the closure of the spill, Operator will collect soil samples from the stormwater control basins and the downstream area to ensure impacts did not migrate. CA date reflects due date of Supplemental Form 19. Date: 05/13/2021

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402683743	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5424225
691201496	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5424223