

Inspection Photos  
John Weigandt Consolidation  
Spill ID 465402 (AC)



**Photo 1 – Spill excavation. Fencing up around open excavation.**



**Photo 2 – Spill excavation.**



**Inspection Photos**  
**John Weigandt Consolidation**  
**Spill ID 465402 (AC)**



**Photo 3 – Spill excavation.**



**Photo 4 – Disturbed area from remediation. Soil impacts still visible on the surface.**



**Inspection Photos**  
**John Weigandt Consolidation**  
**Spill ID 465402 (AC)**



**Photo 5 – Soil impacts still visible on the surface.**



**Photo 6 – Soil impacts still visible on the surface.**