

Inspection Photos
Location Name: State 36-16 TB
Location ID: 468546



Photo 1 – Tank Battery Sign



Photo 2 – Tank Battery



Inspection Photos
Location Name: State 36-16 TB
Location ID: 468546



Photo 3 – Heater Treater, unmarked Riser



Photo 4 – Unmarked Risers at Tanks

Inspection Photos
Location Name: State 36-16 TB
Location ID: 468546



Photo 5 – Pit



Photo 6 – Unmarked Risers at NE Corner of Pit

Inspection Photos
Location Name: State 36-16 TB
Location ID: 468546



Photo 7 – Pit