

Inspection Photos
Location Name: Green 1-1 TB
Location ID: 429231



Photo 1 – Heater Treater, ECD, and Pump House



Photo 2 – Crude Oil Tanks

Inspection Photos
Location Name: Green 1-1 TB
Location ID: 429231



Photo 3 – Produced Water Tanks

Photo 4 – Tank Battery Sign

Inspection Photos
Location Name: Green 1-1 TB
Location ID: 429231



Photo 5 – Pit



Photo 6 – Pit



Inspection Photos
Location Name: Green 1-1 TB
Location ID: 429231



Photo 7 – Unmarked Riser at SE Corner Pit




Photo 8 – Unmarked Risers at Tanks

Inspection Photos
Location Name: Green 1-1 TB
Location ID: 429231




Photo – Stained Soil at Knock-Out Pot