

Inspection Photos
Location Name: Wickstrom #6 CTB
Location ID: 435380



Photo 1 – Tank Battery Sign



Photo 2 – Tank Battery Sign

Inspection Photos
Location Name: Wickstrom #6 CTB
Location ID: 435380



Photo 3 – Tank Battery



Photo 4 – Tank Battery



Inspection Photos
Location Name: Wickstrom #6 CTB
Location ID: 435380



Photo 5 – Heater Treaters




Photo 6 – Unmarked Riser at Pit

Inspection Photos
Location Name: Wickstrom #6 CTB
Location ID: 435380



Photo 7 – Skim Tank NFPA Label



Photo 8 – Holes in Screen.

Inspection Photos
Location Name: Wickstrom #6 CTB
Location ID: 435380



Photo 9 – Unmarked Riser Heater Treater



Photo 10 – Pit