

# Inspection Photos

API: 071-06128

Operator: OGRIS OPERATING LLC

Inspection Date: 5/17/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-06128 | Date: 5/17/2021

## Inspection Photos



**Photo 1.** There is vehicle rutting along the main road. Areas of rutting need to be stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06128 | Date: 5/17/2021



## Inspection Photos



**Photo 2.** There is a plugged culvert along the main road (red arrow). Previous corrective action was not performed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06128 | Date: 5/17/2021



## Inspection Photos



**Photo 3.** The culvert is filled in with sediment causing stormwater to flow down the road. All culverts need to be maintained. Previous corrective action was not performed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06128 | Date: 5/17/2021



## Inspection Photos



**Photo 4.** There is vehicle rutting off the side of the road., This area needs to be stabilized. BMP's are also needed along the steep grade of the road to prevent erosion.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06128 | Date: 5/17/2021



## Inspection Photos



**Photo 5.** There is pieces of blue pipe laying on the road. This debris needs to be disposed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06128 | Date: 5/17/2021



## Inspection Photos



**Photo 6.** The vehicle rutting has not been repaired since previous inspection. Areas of the road are not stabilized and susceptible to further erosion.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06128 | Date: 5/17/2021



## Inspection Photos



**Photo 7.** Stormwater directed from the road has caused a washout at area shown at red arrows.  
Lat/Long:37.09432,-104.94607



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 8.** Facing toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06128 | Date: 5/17/2021