

Inspection Photos
Location Name: Moonshine 36-11-65
Location ID: 417959



Photo 1: Tank Battery Sign



Photo 2: Tank Battery

Inspection Photos
Location Name: Moonshine 36-11-65
Location ID: 417959



Photo 3: Weeds (north of tank battery)



Photo 4: Weeds inside tank battery berm

Inspection Photos
Location Name: Moonshine 36-11-65
Location ID: 417959



Photo 5: Weeds inside tank battery berm



Photo 6: Weeds inside tank battery berm

Inspection Photos
Location Name: Moonshine 36-11-65
Location ID: 417959



Photo 7: Weeds at pumpjack



Photo 8: Weeds at pumpjack

Inspection Photos
Location Name: Moonshine 36-11-65
Location ID: 417959



Photo 9: Weeds at pumpjack



Photo 10: Possible birds nest in horses head at pumpjack

Inspection Photos
Location Name: Moonshine 36-11-65
Location ID: 417959



Photo 11: Unused risers; weeds