

Inspection Photos

API: 071-06339

Operator: OGRIS OPERATING LLC

Inspection Date: 5/17/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06339 | Date: 5/17/2021

Inspection Photos



Photo 1. There is vehicle disturbance off the side of the road. The disturbance needs to be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06339 | Date: 5/17/2021

Inspection Photos



Photo 2. There is vehicle rutting along the main road. Areas of rutting need to be stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06339 | Date: 5/17/2021

Inspection Photos



Photo 3. There is a water leak at the wellhead that needs to be repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06339 | Date: 5/17/2021